

THERMO-HYGROMETERS

DIGITAL MAX/MIN THERMO HYGROMETER



Current Indoor and Outdoor temperature,
and indoor humidity in the display
Indoor/Outdoor min. / max. measurement by pressing the MAX./MIN key

Measuring range:
IN: 0°C to + 50°C / 1°C (+32°F to 122°F)
OUT: - 50°C to + 70°C / 1°C (-58°F to +158°F)
Indoor hygro range: 20 to 98 RH / ± 5%
Supplied with 1,5 m cable sensor probe for outdoor min.
and max temp. measurement
Size: 123 x 70 x 20 mm,
Battery: 1 xAAA (1,5VDC) battery included

Code

BOE 326

DIGITAL THERMO- / HYGROMETER



Dual LCD display with indoor temp. and relative
indoor humidity at the same time.

Measuring range:
Indoor temp.: 0°C to + 50°C /1°C
Rel. humidity indoor: 25% to 95%/1%
with battery (AAA, 1pc.)

Code

BOE 330

DIGITAL THERMO-HYGROMETER & CLOCK



Display Indoor Temperature and Humidity, Outdoor temperature
record the maximum and minimum temperature and humidity
°C and °F switch
Freeze alert from -1°C to +4°C

Temperature measuring range:
Indoor: -10 to + 50°C (+14 to +122 °F)
Outdoor: -5 to + 70°C (-58 to + 158°F)

Humidity measuring range:
20 – 99 %RH

Accuracy:
± 1°C,
± 5% RH

1 x battery (AAA) incl.

Code

BOE 327